



IN REPLY REFER TO:

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Mr. Darby
County Surveyor
Douglas County, Oregon

May 14, 1964

Dear Mr. Darby:

The following are the bearing and distances to the trees marked by your office for the $\frac{1}{4}$ sec. cor. of secs. 19 and 20, T. 23 S., R. 6 W. which was moved by my crew to its proper position.

A fir, 17 ins. diam., bears N. 30* E., 68 ft. dist., mkd. $\frac{1}{4}$ S20 CS BT.

A hemlock, 11 ins. diam., bears N. 2* W., 87 ft. dist., mkd. $\frac{1}{4}$ S19 CS BT.

We also marked a tree:

A fir, 24 ins. diam., bears N. 85* E., 35.6 ft. dist., mkd. $\frac{1}{4}$ S20 BT.

The marks on the trees marked by Eggan in the 1957 resurvey by BLM. were destroyed.

The cor. common to secs. 34 and 35 only on the S. bdy. of T. 22 S., R. 8 W. has been found by James Jelley. This is a corner which we are not going to monument, since it control private lands only and we do not need it for control. Mr. Jelley posted bearing tree tags on the BT's and drove a wooden post at the corner point.

Very truly yours

Floyd A. Brooks
Floyd A. Brooks
Cadastral Surveyor

FILED
RECEIVED

MAY 18 1964

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 52/102³⁰