

REN.

T 23 S R 7 W

COR.  
SECS.

2/1  
11/12

AT COR. FD. HAINES "T" IRON

WITH 6" DIAM. WOODEN STAKE ALONGSIDE

FD. CEDAR TREE (NOW 36" DIAM.)

N 35° E 53 1/2 FT. - LOWER SCAR NOT  
COMPLETELY HEALED OVER, - GOOD

SCRIBING VISIBLE "BT" - TREE IN  
GOOD CONDITION.

FD. CEDAR STAKE S 38° W 29° FT. -

CENTER COMPLETELY BURNED AWAY -  
SCAR VISIBLE ON N.E. FACE.

FD. CEDAR STUMP S 18° E 28 1/2 FT. -

CENTER COMPLETELY ROTTED AWAY, -  
NO SCARS VISIBLE.

NO TRACE FD. OF MAPLE TO N.W.

ALONGSIDE "T" IRON AT COR. SET

IRON PIPE WITH BRASS CAP MKD.

"COUNTY SURVEYOR'S OFFICE 1964

T 23 S R 7 W S 2 | S 1 " - ERECT

S 11 | S 12  
ROCK MOUND AROUND CORNER.

BLAZE & SCRIBE 3 NEW TREES:

26" MYRTLE S 53° E 76° FT.

MKD. " T 23 S R 7 W S 12 CS BT "

20" MAPLE N 10° W 45 1/2 FT.

MKD. " T 23 S R 7 W S 2 CS BT "

30" MAPLE S 30° W 47 1/2 FT.

MKD. " T 23 S R 7 W S 11 CS BT "

COR. IS IN DRAW, APPROX. 40 FT. W.  
OF SMALL STREAM.

M.L.B.  
&  
D. [unclear]

(SEE REN. # 94)

OCT. 9, 1964

M.S. S. FILE NO. 51170

#113