


PUBLIC LAND CORNERS

Index 1231

MEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH



TOWNSHIP 3 S RANGE 3 W
 SECTION 19 CORNER W 1/4
 COUNTY WASCO COUNTY OREGON

GLO SURVEY RECORD

DATE: 1987
 CORNER POST

ACCESSORIES:

	BEARING-	LINKS--	FEET-
1" FIR	N 10° E	25	
1" FIR	S 60° W	25	

SURVEY RECORD
 DATE:

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

NO TRACE OF THIS PT

NO TRACE OF THIS PT

FOR THIS SURVEY THE ORIGINAL BEARS
 THE ORIGINAL BEARS TO BE AN ERROR IN
 ORIGINAL FILE AND THIS BEARING IS CORRECT

PRESENT CONDITION:

CORNER SET: 2" x 2.5" BRASS MAGNETIC DECLINATION: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-
W	25.8

CS 53 / 1-19
 A

ACCESSORIES ADDED THIS DATE:

	BEARING-	FEET	ORIG. BT	*W-NAIL	PLATE	BRASS DISC
42 " FIR (ORIGINAL SET)	N 64° W	12.8	X	X		
54 " FIR STUMP	N 28° E	32.4	X	X		

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

DESCRIPTION OF GROUND COVER AND GROUND SLOPE AT CORNER: CG FIR TO WEST,
LOWED TO THE EAST

FROM CORNER NORTH: _____

SOUTH: _____

EAST: _____

WEST: _____

WORK DONE FOR W. T. CO.

BY: Hale
ENGINEER - SURVEYOR

DATE: FEBRUARY 26, 1957

ASSISTED BY: DONALD WARNER

RONALD YOUNG

CORIN WALLER

UNDER SUPERVISION OF:

COPIES SENT TO: _____

SEAL PAGE 3

CS 53 / 1-19

B