

Survey for W. A. Woodard Lbr. Co., by Gilbert Gardner
in
July-December, 1955
Secs. 25-26-35-36

1/4 Cor. W. side Sec. 24

Found 1" iron pipe in fence corner
30" W. Oak N 50°E 139.9 ft. now gone
10" W. Oak S 30°W 126.7 ft. now gone
Fence Cor. & I. Pin were set before BTs were destroyed

(64) ✓

1/4 Cor. N. side Sec. 24

Found stone
1 Fir BT standing 28" Fir N 84°E 28.0 ft. 18" when marked
Fence running East and West from Cor.

(65) ✓

Sec. Cor. NW Cor. Sec. 26

Found old Cedar Stake badly rotted in fence cor.
BT stumps badly burned

(66) ✓

1/4 Cor. N. side Sec. 26

Set 1/4 Cor. stake 4"x4"x3' from which:
14" D. Fir brs. S 12 1/2°E 10.0 ft. marked 1/4 S BT
no other trees available
set at proportional distance

Sec. Cor. common to Secs. ^{23,} 24, 25 & 26

Found stone in fence cor.
BTs all gone
Stone marked with "X"

(67) ✓

1/4 Cor. on E. side Sec. 26 & W. side Sec. 25

Found 9" Fir BT N 69°E 25.1 ft. now 24" markings visible, alive and standing
Set new BT marked 1/4 S BT, 5" D. Fir brs. N 86°W 14.2 ft.

Sec. Cor. common to Secs. 25, 26, 35 & 36

Set new BTs for Secs. 25, 26, 35, 36
10" D. Fir S 30°W 13.8 ft. marked S 35 BT
10" D. Fir S 8°E 29.2 ft. " S 36 BT
10" D. Fir S 72°E 13.9 ft. " S 25 BT
10" D. Fir N 62°W 6.6 ft. " S 26 BT
Set at proportionate distance

1/4 Cor. on S. side Sec. 26

Set 2" I. Pipe from which 2 new BTs brs:
14" I. Cedar N 50 1/2°E 35.0 ft.
24" I. Cedar S 80°W 110.6 ft. marked 1/4 S BT
Set at proportionate distance

CS 53/1-67