

# T 20 S - R 11 W

Post and other bearing trees gone. Reestablish this corner by setting a yew wood post 4" x 4" x 5" marked S 2 19 S on N.E., S 3 R 6 W on N W, S 10 C S on S W, and S 11 on S E faces from which

Above 12 inch yew now 24 inches bears S 35° W 12 lks., orig. BT  
Fir. 40 " " " 50 " " " N 37½° W 41 lks (not 47 lks.)

original B.T.  
A fir 48 ins. diam. marked T 19 S R 6 S 2 C S B T N 68° E 44 lks. .  
A yew 10" " " " T 19 R 6 W S 11 C S B T brs. S 24° 45' 82 lks.

Present Fred Burgess and Jesse Hooker  
Feb 15, 1934

Earl G. Muir

Recorded by G H WAGGONER

✓ #30

The ¼ Sec. cor. bet. secs. 5 and 6 Tp 20 S R 11 W  
At this corner I find the bearing tree described as a fir 12 ins. diam. bearing East 9 links showing original marks. Set cedar post 4 x 4 inches marked C S and mark new bearing trees as follows:

A fir 18 in. diam. marked C S B T brs. N 33° W 12.9 ft.  
A " 16 " " " " " " " " " S 12½° E 16.3 ft.  
A " 18 " " " which seems to have been marked as a bearing tree brs. N 75° W 8.6 ft.

Present Clarence Johnson, William and Ben Gibson  
Apr. 16, 1934

G.H.Waggoner

The ¼ Sec. cor. bet. secs. 31 and 32 Tp 19 S R 11 W  
At this corner I find the stump of the Hemlock bearing tree 20 ins. diam. bearing S 7° E 52 lks. showing original scribing. Also stump of Maple 8" S 62° W 54 lks marks rotted off also old stake set by McCausland  
At south side of old stake drove an auto axle 1½ ins. diam. 24 inches long driven to the surface.

Apr. 16, 1934

Present Clarence Johnson, Ben and William Gibson  
G.H.Waggoner  
Dep. Co.Sur.

The ¼ Sec. cor. on the South bay of sec. 32 Tp 19 S R 11 W  
At this corner I find an iron pipe, in order to verify this pipe I chopped out the marks of the bearing tree described as a fir 6 ins. diam. Now 30 ins. diam. and found the original marks. From said iron pipe this tree brs. N 51° E 73 lks.  
Find no trace of Alder bearing tree.

Present Joe Ben and William Gibson, Martin et al  
Apr. 16, 1934

G. H. Waggoner  
Dep. C S

✓ 31

1 COPY