

E 1/16

Corner on South line Section 26-20S-5W = Point "P"

Set 1" x 30" aluminum pipe for corner by single proportionate method.

Referenced by Glen McChesney (Weyerhaeuser Method)  
Declination 20°

10" Yew	N 15° E	7.0'
44" Fir	S 34° W	37.7'

26	25
35	36

Corner common to Sections 25, 26, 35 and 36-20S-5W

GLO Survey Record

Post		Gone
60" R. Fir	N 45° E	39 lks 60" snag, badly burned.
6" R. Fir	S 20° E	64 lks 12" x 3' stub - old axe marks,
6" R. Fir	S 05° W	45 lks No trace.
30" R. Fir	N 68° W	11 lks 46" Fir - upper face burned, lower face not opened.

County Survey Record, 1935

Post		Found charred stake
20" Fir	N 38° W	56 lks Found - Scribing visible.
38" Fir	S 82° W	11 lks Found.
12" Fir	S 20° E	64 lks 12" x 3' high stub. Axe marks.

Found 3" square Chinquapin post for corner.

Referenced by Glen McChesney (Plates and "W" nails only).  
Declination 20°

3" Fir	N 56° E	10.5'	
26" Fir	S 03° E	49.4'	
46" Fir	N 81° W	7.0'	Original BT

No reference to SW

CS 53 / 1-87