

RENEW $\frac{78}{1817}$ T33S R6W

FOUND -

ORIG. 20" NOW 39" SNAG FIR, N52°W

19.1' NO SCRIBING FOUND. ORIG. 20" NOW SNAG

30" FIR, N 86° E 14.5' SHOWS OLD

AXE MARKS NO SCRIBING FOUND,

ORIG. 19" NOW 16" LAUREL SNAG SHOWS

OLD ROTTED FACE & AXE WORK NO

SCRIBING FOUND. WE FIND STUMP HOLE

FOR ORIG. SW BT.

NOTE - THIS IS IN OLD BURN AREA

THE FIRS WERE PROBABLY BARK

SCRIBED. RING COUNT CHECKS FOR

SIZE & ALL CHECK RECORD BEARING

& DISTANCE.

SET BRASS CAP AT CORNER & MARK

DOUGLAS CO SURVEYORS OFFICE 1763

57 58

T33S R6W

518 517

NEW BTD.

6" CHINOQUIPIN BEARS S 70° E 7.9'

SCRIBED 517 T33S R6W CS BT.

11" LAUREL BEARS S 75° W 35.2'

SCRIBED 518 T33S R6W CS BT

3" R. FIR BEARS N 70° W 20.0'

SCRIBED CS BT

5" R. FIR BEARS N 29° E 20.4'


SCRIBED 58 CS BT

C.S. No. 53/8-2

July 2 - 1963

H
M
B.S.S.

DIETZEN NO. 385-B



Jensen

UNITED STATES
DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
District Office
1133 S. Riverside
Medford, Oregon

IN REPLY REFER TO:
36-110- NW-A
9180 Cad. Sur.

JUN 24 1963

County Surveyor
Douglas County Courthouse
Roseburg, Oregon

Dear Sir:

Enclosed is a copy of a report pertaining to the S. E. corner of Section 7, T. 33 S., R. 6 W., Will Mer, recently submitted by one of our foresters.

In view of the slight evidence remaining, it is requested that you visit the location, evaluate the evidence, and, if possible, perpetuate the corner. Your cooperation is most sincerely appreciated.

Yours truly,

Kenneth W. Jensen
Kenneth W. Jensen
Assistant District Manager

Attachment

FILED
RECEIVED

JUN 26 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.


C. S. File No.

A1-258
7-29-66

LOCAL RECORD
CORNERS OF THE CADASTRAL SURVEY GRID

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

T. 33 S R. 6 W , W Mer., ORE. State.



SYMBOLS

- Official corner found.
- Probable corner found, authenticity doubtful.
- Corner searched for and not found.

Reported By E. H. Hunt
Signature
Title Forester
Date 6-24-63

Corner common to Secs. _____, _____, _____ & _____ is a mound of stone, tree, rock, fire pit, iron pipe, _____ size _____

LEGIBLE MARKS ON BEARING OBJECTS

KIND	D. FIV	D. FIV	madrox	madrox
SIZE				
BEARING	N 52° W	N 46° E	S 78° W	S 75° E
DISTANCE	29.45	22.45	56.45	22.45
BT TAG POSTED	yes			yes

ADDITIONAL INFORMATION

All BT'S FIT FOR BOUND DIST.
NO SCRIBING FOUND - AT
INTERSECTION OF LINES. NE
MADROX BT FACED - BUT
FACE SHOWS OLD CHIPPING -
WORK ERoded AND SASSURED
CONVEYS MARK ON NE BT
CORNER IN NEED OF IMMEDIATE
ATTENTION

INTERIOR--BONNEVILLE POWER ADMINISTRATION, PORTLAND, OREGON (OVER)

REVIEWED
JULY
2-1963

FILED
RECEIVED

JUN 26 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 53/8-2