

REM. T 24 S R 3 W W 1/4 S 19 ONLY

(ON E. LINE SEC. 24 T 24 S R 4 W)

FD. G.L.O. BRASS CAP SET

IN 1950.

THE 13" RED CEDAR S 84 1/2° E

59 1/2 FT ALIVE & IN GOOD CONDITION.

SHOWS GOOD SCAR.

FD. SAWED STUMP OF 32" FIR

S 69 1/2° E 19 FT. - FACE STILL ON

STUMP - PITCHED OVER.

BLAZE & SCRIBE ONE NEW TREE:

12" HEMLOCK N 77 1/2° E 55 3 FT.

MKD. " 1/4 S 19 CS BT "

JUNE 13, 1963

M.G.
V.T.
M.S.

Milo P. Godfrey

JUN 13 1963

RECORDED

COUNTY SURVEYOR

+ * (circled) ✓

FD. OK. COR. SECS. | S18 T 24 S R 3 W
| S19

ON E. LINE SEC. 24, T 24 S R 4 W

FD. BRASS CAP IN PLACE

BOTH B.T.S MKD IN 1950 & THE ORIG.

S.E. BT. ALIVE & IN GOOD CONDITION.

FD. OK. E 1/4 COR. SEC. 24 (ONLY)

T 24 S R 4 W

BRASS CAP & BOTH B.T.S IN

GOOD CONDITION

(SEE OVER)

C.S. File No. 53/9-101

FD. O.K. COR. SECS $\frac{S19}{S30}$ T24SR3W

ON E LINE SEC. 24, T24SR4W

BRASS CAP & 3 ORIG. B.T.S
(ALL THAT WERE FD. ALIVE IN 1950)
ARE IN GOOD CONDITION ✓

FD. O.K. CC $\frac{S24}{S25}$ T24SR4W

ON W. LINE SEC. 30, T24SR3W

BRASS CAP & S.W. B.T. MKD. IN
1950 IN GOOD CONDITION. — N.W. TREE
(1950) GONE. BOTH ORIG. TREES
(FD. IN 1950) ALIVE & IN GOOD CONDITION. ✓

FD. O.K. W $\frac{1}{4}$ SEC. 30, T24SR3W

ON E. LINE SEC. 25, T24SR4W

BRASS CAP & BOTH B.T.S
IN GOOD CONDITION. — S.E. TREE
IS RED CEDAR, NOT HEMLOCK. ✓

FD. O.K. E $\frac{1}{4}$ COR. SEC. 25, T24SR4W

(ON W. LINE SEC. 30, T24SR3W)

BRASS CAP IN MOUND OF ROCK
& BOTH B.T.S IN GOOD CONDITION. ✓

DIETZEN NO. 385-6