

REN.

T 27 S R 4 W

COR. 26 | 24
SECS. | 25

AT COR. FD, PIPE WITH BRASS
CAP SET IN 1917 SURVEY,

FD. 12" FIR N 61 1/2° E 10 1/2 FT. - NOW
SPLINTERED SNAG - BADLY BURNED
OLD FACE, - NO SCRIBING LEAF

FD. 20" FIR S 40 1/4° E 25 1/2 FT. -
NOW UPROOTED & DEAD.

BLAZE & SCRIBE NEW TREES:

4" MADRONE S 76° E 21 1/2 FT.

MKD. "S 25 C S BT"

25" INCENSE CEDAR N 63° E 153 1/2 FT.

MKD. "T 27 S R 4 W S 24 C S BT"

OCT. 10, 1963

Milo E. Godfrey

M.G.
W.S.
M.D.
M.S.
J.H.

+ X ✓

FD. O.K. - 1/4 S 24 T 27 S R 4 W
S 25

BRASS CAP & BOTH B.T.'S MKD.

IN 1917 FD. IN GOOD CONDITION.

FD. O.K. COR. 23 | T 27 S R 4 W
SECS. 26 |

ROAD & 3/4" IRON ROD AT COR. IN GOOD
CONDITION. - ALL 3 TREES MKD. IN

1958 ALIVE & IN GOOD CONDITION. C.S. FILE NO. 53/33' 13