

REN. T 26 S R 3 W  $\frac{1}{4}$  S  $\frac{1}{4}$  S

FD. 10" FIR (DEAD) N 83° E 24 2 FT.

- PREVIOUSLY OPENED - GOOD SCRIBING

"  $\frac{1}{4}$  S C S " VISIBLE ON PARTIALLY ROTTED  
FACE. - (EPPSTEIN'S B.T.) Ren. # 11

FD. WHITE OAK (NOW 20" DIAM.)

S 71° W 35 2 FT. - PREVIOUSLY OPENED -  
SCRIBING VISIBLE "B" ON BADLY ROTTED  
FACE. - (GERMOND'S B.T.)

DID NOT FIND IRON PIPE SET  
BY EPPSTEIN AT COR.

AT COR. SET IRON PIPE WITH BRASS  
CAP MKD. " COUNTY SURVEYOR'S OFFICE

1963 T 26 S R 3 W  $\frac{1}{4}$  S  $\frac{1}{4}$  S

BLAZE & SCRIBE NEW TREES!

10" DOUG. FIR N 37° W 24 2 FT.

MKD. "  $\frac{1}{4}$  S 30 C S B T "

24" DOUG. FIR N 54° E 27 0 FT.

MKD. "  $\frac{1}{4}$  S 29 C S B T "

COR. IS 25 FT. SOUTH OF E+W  
FENCE LINE.

REN # 11

*M. G. W. S. M. S.*

DEC 12, 1963

M. G.

W. S.

M. S.

+ X

W.D. FILE NO. 53/3854

Section 4 29:30 <sup>Top</sup> 265 Egs 3

Date 12-04-63

How was corner identified? BY SCRIBES ON 10"


Exc (Lead AND COTTON) OAK 4" Cotton

Condition of corner:

Best route to reach corner: Turn on Little River Rd  
Then Turn onto Buckhorn Rd. go 90 Yds.  
on N side of Rd Behind BARN.

Other Remarks:

Signed  
Roy A. Heichel



RENEWED DEC 12  
1963  
Ohio C. Bradley

Quadrant	NE	NW	SE	SW
Species & Size	10" Fir			
Dist. & Bearing	24.7'	N 83° E		
Condition of Scribe	Good			
Original or Resurvey	Resurvey			
Appearance of B.T.				
Tags, Marks, etc.				