

REN. T 26 S R 3 W

COR. 30/29
SECS. 31/32

FD. BLACK OAK (NOW 36" DIAM.)

N 62° W 21 8 FT - PREVIOUSLY OPENED

- GOOD SCRIBING "30 CS" VISIBLE ON

OLD FACE,

Ren. #12

FD. BLACK OAK (NOW 29" DIAM.)

N 44° E 123 0 FT. - TOP BROKEN OUT

OF THIS TREE, BUT STILL ALIVE -

PREVIOUSLY OPENED - BOTH OLD FACES

VISIBLE, BUT SCRIBING GONE.

FD. BLACK OAK (NOW 30" DIAM.)

N 80° W 19 8 - OPENED MANY YEARS

AGO & FACE ROTTED AWAY (ORIG. B.T.)

AT COR. SET IRON PIPE WITH

BRASS CAP MKD. "COUNTY SURVEYOR'S

OFFICE 1963 T 26 S R 3 W S 30 | S 29 "

S 31 | S 32

BLAZE & SCRIBE NEW TREES:

8" MADRONE S 49° E 47 2 FT.

MKD. "T 26 S R 3 W S 32 CS BT"

8" MADRONE S 82° W 47 0 FT.

MKD. "T 26 S R 3 W S 31 CS BT"

25" BLACK OAK N 8° W 45 4 FT.

MKD. "T 26 S R 3 W S 30 CS BT"

16" BLACK OAK N 25° E 88 5 FT.

MKD. "T 26 S R 3 W S 29 CS BT"

A FENCE COR. (FENCES SOUTH & EAST)

BEARS S 70° W 4 FT.

REN. #12

DEC. 12, 1963

Mild C. Hoff

M.G.


W.S.

C.S. No. S. 53/32-5

+ X O

Section 29-30-31-32 Twp 26 S 3 1

Date: 12-06-63



How was corner identified? By A witness tree scribe visible

Condition of corner: _____

Best route to reach corner: Turn onto Little River Rd Then Turn onto Buckhorn Rd go approx. 1 mile it is on LT side of Rd. in fence line on top of hill.

Other Remarks: _____

Quadrant	NS	WN	SE	SW
Species & Size	36" OAK Now was 30" OAK			
Dist. & Bearing	N 62° W 21.8			
Condition of Scribe	Fair			
Original or Recurveyed				
Appearance of M.F.				
Sup. <u>17</u> of <u>17</u>				

Harry R. Heichel
Signed

RECORDED
DEC 12 1963
Twp 26 S R 3 E S 1