

REN. T 26 S R 3 W.  $\frac{1}{4}$  S  $\frac{1}{32}$

AT COR. FD. ROCK MKD. " $\frac{1}{4}$  S"

ON EAST FACE. - ALSO FD. CEDAR

STAKE - ROTTED OFF & LYING ON

GROUND BESIDE ROCK,

FD. BLACK OAK (NOW 28" DIAM.)

S 33° E 83<sup>3</sup> FT. - HAS BEEN OPENED

PREVIOUSLY & FACE BADLY ROTTED. -

FD. PORTION OF REVERSE SCRIBING ON  
OVERGROWTH.

FD. STUMP & ROTTED REMNANTS  
OF OAK STUMP N 35° E 21<sup>2</sup> FT. -

(ORIG. N.E. B.T.)

NO TRACE OF ORIG. N.W. B.T. FD.

ALONGSIDE ROCK AT COR. SET

IRON PIPE WITH BRASS CAP MKD.

"COUNTY SURVEYOR'S OFFICE 1963

T 26 S R 3 W  $\frac{1}{4}$  S  $\frac{1}{32}$

BLAZE & SCRIBE NEW TREES:

16" DOUG. FIR S 70° E 33<sup>2</sup> FT.

MKD. " $\frac{1}{4}$  S 32 CS BT"

12" DOUG. FIR N 49° E 26<sup>2</sup> FT.

MKD. " $\frac{1}{4}$  S 32 CS BT"

NO TREES AVAILABLE WEST OF  
LINE.

COR. LIES 4<sup>6</sup> FT. EAST OF

N. & S. FENCE LINE.

DEC. 24, 1963

REN #19

W. E. Godfrey

M. G.

W. S.


M. S.

C. S. F. 100.

53/38

+ X

Section 14 31:32 265 3 7 1963



How was corner identified? By Bearing Tree with Blaze

Mark. Cor. is a 6" x 10" x 10" stone marked 14522.  
Tree is rotten. Scribe is not visible  
 Condition of corner: \_\_\_\_\_

RENE 211 1/2  
 D.E. C. 1/2  
 ON 1/2

Best route to reach corner: Turn onto Little River Rd. Turn  
onto Buckhorn Rd. go approx 1 1/2 miles cor is approx  
1150 E of the Rd. just on the east side of fence

Quadrant	NS	NW	SE	SW
Species & Size	24"	B. DAK		
Dist. & Bearing	533° E	83.3'		
Condition of Scribe	Bad			
Original or Resurvey				
Appearance of B.T.				
Tags, Marks, etc.				

Other Remarks:

Ray A. Reichel  
 Signed