

Benguel 53/52 T30S R7W

Found:

10" D. Fir 140W 18" N12E 20⁵
Tree had been opened for scribe
"S"
Opened more for T

No trace of
10" Fir 525W 23²

Reviewed:

Set Brass cap at $\frac{1}{4}$ Sec. corner
county surveyors office
T30S R7W

$\frac{1}{4}$ 53/52
1966

New Bearing Trees

21" P. Fir S17E 47²
Scribed $\frac{1}{4}$ S 2 C.S. BT
No other good trees nearby in sec 3
Relabeled & Rescribed

18" D. Fir N12E 20⁵
Scribed $\frac{1}{4}$ S 2 C.S. BT

This cor lies at bottom of 15' Rock
bluff,
ON VERY steep West slope about
75' East of spring branch.

7-11-66
~~2222~~
~~2222~~
TCC

OK J.W.B.

#104
X

C.S. No. 53/40-84