

Renew $\frac{1}{4}$ COR $\frac{11}{14}$ T30S R7W

Fd at cor Both BT's & CORNER TREE

25 Recorded in Renewal # 2 by Briggs
in 1892 as follows -

5" Red Fir CORNER TREE, Now 16" shows
very faint scar, has been used as fence
CORNER.

4" D. Fir, Now 7" stump North 4 $\frac{1}{2}$ ft
cut open & Fd " $\frac{1}{4}$ 5" scribe.

5" D. Fir, Now 16" snag S. 5 $^{\circ}$ W. 3 $\frac{3}{4}$ ft
cut open & Fd "B" scribe. We Fell
snag to prevent possible damage to
corner. Set Witness^{cop.} I.P. & BRASS Cap
MKd "COUNTY SURVEYOR'S OFFICE
1964 W.C. 4 FT. E. $\frac{1}{4}$ 5 11"
T30S-R7W $\frac{1}{4}$ 5 14". This Monu-
-ment is 4 $^{\circ}$ ft West of Cor. tree.

New B.T.'s -

20" D. Fir N. 51 $^{\circ}$ E. 14 $\frac{1}{2}$ ft.

Mkd. W.C. $\frac{1}{4}$ 5 11 CS BT

22" D. Fir S. 15 $^{\circ}$ W. 15 $\frac{1}{2}$ ft.

August 26, 1964

V.R.T.

M.D.

J.B.

V.R. Tracy

+ QX

C. S. File No. 53/40-89