

Renewal $\frac{1}{4}$ S11 $\frac{1}{2}$ S12 T30S R7W

Fd at Cor. 22" Oak snag S. 28° E

19⁸ ft., opened & Face Rotted off.

14" Fir snag S. 25° W. 24⁵ ft as

Recorded in Renewal #18. Set

1" I.P. & Brass Cap MKd - "County

SURVEYOR'S OFFICE 1964 T30S

R7W $\frac{1}{4}$ S11 $\frac{1}{2}$ S12 " & New BT's -

25" cedar N. 43° W. 39² ft.

Mkd. $\frac{1}{4}$ S11 CS BT

16" W. Oak N. 51° E. 101² ft.

Mkd $\frac{1}{4}$ S12 CS BT.

August 25, 1964

V.R.T.
M.D.

V.R.T. Fray

+KO ✓

U.S. FILE NO. 53/40-90