

REM. T 26 S R 5 W

$\frac{1}{4}$ S29
S32

FD. MADRONE TREE (NOW 9" DIAM.)
N 47° W 6 $\frac{1}{2}$ FT. - CUT OPEN SCAR &
FD. FRAGMENTS OF SCRIBE MKS. AT
EDGES OF OLD ROTTED FACE.

FD. FIR STUMP (NOW 24" DIAM.)
S 55° E 22 $\frac{1}{2}$ FT. - OPENED SCAR & FD.
BOTTOM EDGE OF FACE, BUT NO SCRIBING.

FD. FIR STUMP (NOW 24" DIAM.)
N 66 $\frac{1}{2}$ ° E 25 $\frac{1}{2}$ FT. - SHOWS GOOD SCAR. -
DID NOT OPEN. #13

(THESE 3 ARE FLEISER'S TREES)

FD. ROTTEN REMNANT OF OAK
STUMP S 53° E 19 $\frac{1}{2}$ FT. - ORIG. BT.
NO TRACE FD. OF ORIG N.E. TREE.

AT COR. SET IRON PIPE WITH BRASS
CAP MKD, "COUNTY SURVEYOR'S OFFICE
1963 T 26 S R 5 W $\frac{1}{4}$ S29"
S32

BLAZE & SCRIBE NEW TREES:

10" MADRONE N 59° E 12 $\frac{1}{2}$ FT.
MKD. " $\frac{1}{4}$ S 29 CS BT "

11" DOUG. FIR S 75° W 16 $\frac{3}{4}$ FT.
MKD " $\frac{1}{4}$ S 32 CS BT "

NOV. 15, 1963

#13

Milo

M.G.

M.S.

+2

Doc
49/125
53/51a