

Renewal S32/S33 T30S R9W  
SS/S4 T31S

Found:

- 10" Douglas Fir N40W 15' N50E 66  
I find this tree to be 10T  
Shows good score.
- 33" Douglas Fir N40W 10' S39 1/2 W 40E  
I find this tree to be 10E  
Shows fair score.
- 11" Douglas Fir N40W 15' S85 1/2 W 29E  
Shows good score.
- 12" Fir (DOWN) N85W 39E  
opened for scribe "BT"

Renewal:  
Set Brass cap at Sec Cor MAD  
county Surveyors office

T30S R9W  
S32/S33  
SS/S4  
T31S  
1965

New Bearing trees:

34" Douglas Fir N71W 42E  
Scribed: T30S R9W S32 CS BT

I could not match distances good  
so I took 4 Bearings + two  
distances.

11-30-65

G.M.C.  
D.C.C.  
R.W.G.

+89-100

+X 39-121 \*

C.S. File No. S3/S3-35

DIETZGEN NO. 388-6