

Renewal

$\frac{1}{4}$ $\frac{S33}{S4}$

T30S R9W
T31S

Found:
20 X 12 X 10" stone $\frac{1}{4}$ on N. Face
36" Fir N $2\frac{1}{4}$ W $14\frac{5}{8}$

This tree Blown down on Face.
Shows two good Faces

10" Hemlock Now 21" S79 $\frac{1}{2}$ E 12 $\frac{5}{8}$

Tree Shows Scar,

Finding Stone and getting late
I did not open tree.
Call very good on Stream.

Renewal:

Set Brass cup at $\frac{1}{4}$ cor. MAD
County Surveyors office

T30S

$\frac{1}{4}$ $\frac{S33}{S4}$ R
W

T31S

1965

New Bearing Trees:

21" Hemlock S79E 12 $\frac{5}{8}$
scribed $\frac{1}{4}$ S4 CS BT

56" Cedar N38E 21 $\frac{5}{8}$
scribed $\frac{1}{4}$ S33 CS BT

11-30-65

J. M. G.
J. C. G.

J. M. G.

*90-T30

+ X*40-T31

CS 53 | 53-34

C.S. FILE NO.