

14/13
23/29

T303 R9W

Renovial

Found:

25" D. Fir New stump N 52° W 38' 2"
shows BT scar + Parks of Park scribe

23" Cedar New 23" N 77° E 15' 2"
shows scar (slight)

16" W. Fir New stub S 73 1/2° E 46' 2"
Scribe visible

6" W Fir New 7" S 15° W 27' 2"
Scribe visible "R9W"

Found 1" Iron Pipe under 20" of Earth
still standing upright. Set Brass cap directly
over iron pipe. Ren #19

Renovial

Set Brass cap at Sec cor M&D
County Surveyors office

T303 R9W

514/513
523/529

1970

Next Bearing Trees

11" D. Fir N 44° W 63' 0"
Scribed T303 R9W 514 CS BT

8" W. Fir S 75° E 51' 2"
Scribed T303 R9W 529 CS BT

9-10-70

D. W.
J. W. B.

~~Signature~~

#101 ✓

C. S. File No. 53/53-41

DIETZGEN NO. 385-6