

Renew COR. #6 of HES 190 \rightarrow N. $\frac{1}{16}$ S 10 T 205 R 11 W

Fd. Remains of old cedar post in place
& O.B.T.s as follows -

ORIG. 12" Now 20" FIR N. 65° E. 31 $\frac{1}{2}$ ft.
alive - shows old scar & some more
Recent chopping - see Tag.

ORIG. 8" Now 14" FIR N. $50\frac{1}{4}^{\circ}$ W. 11 $\frac{1}{2}$ ft.
Down - open & scribe visible on
open blaze - at cor. point set 1"
I.P. & BRASS cap MKd. "COUNTY

SURVEYORS OFFICE 1970
T 205 N. $\frac{1}{16}$ S 10 COR # 6 HES 190

R 11 W" & MK. New B.T.S -
24" SPURCE S. 36° W. 27" ft.
MKd. "6 HES 190 N. $\frac{1}{16}$ S 10 CS BT"
14" D. FIR. N. 50° W. 33 $\frac{1}{2}$ ft.
MKd. "6 HES 190 N. $\frac{1}{16}$ S 10 CS BT"

This COR. Lies on VERY steep
N.E. Slope approx 50 ft. west
of small Ravine course North

April 1970

URT
JAH
VDP

V.R. Tracy

O.K.
J.W.H.

0#96

C. S. File No. 53/66-5