

Benewah # $\frac{819}{1716}$ T205 R11W

Found

23" Maple Now 29" S56E 215'

Shows scar

30" cedar now? S41W

No trace of I.P.C. in Pasture.
Probably plowed up.

I can not get across creek at
this time. By using two Bearings
& 1 Dist. also taken from property
corner I set wit. cor.

Benewah

Set Brass cap at Wit. Cor. M&A
County Surveyors Office

T205 R11W
W.C. 90° North to

$\frac{819}{1716}$

1969

Relazed & Rescribed

29" Maple S79E 178'
Scribed W.C. T205 R11W S16 65 FT

No other Trees Available

Note:

This cor lies on North Bank of
creek, approx 15' from E of creek
Also post set along side Brass cap

9-23-69
JWB
RWB
WCB

O.K.
JWB

#65

G.S. File No. 53/66-26