

Renewal  $\frac{12}{12}$  6 T21S R10-9W

Found:

22" D. Fir NAW 50° 53° W 42°  
Shows Scar.

36" D. Fir NAW 36° 41° W 28°  
Shows good Scar

Renewed Tree

20" D. Fir NAW 80" 3 20 W 67°  
Pitbed over Scoring Visible

Brass Cap at See car M&P.

General Land Office

T 21 S  
S 1  
S 12  
8 1001

1919

Renewal

New Bearing Tree

17" D. Fir N 59° E 40°  
Scarred T 21 S R 9 W 56 CS 8 T

Note

I Renew this car because of new Rd. to be built. S.W. Tree is on top of ridge and will probably be taken out.

Rd 57A. P. line 72 + 30

O.K. J.W.

9-30-69

J.W.

11/2/69

#17-T20-9W

#8-T21-9 #32-T21-10

C. S. File No. 53/66-30

DIETZSEN NO. 385-6