

Renew Sec. Cor T195 533 | 534 R9W

Fd. 1921 G.L.O. BRASS CAP ON
BROKEN CONCRETE FILLED I.P. IN PLACE
of ~~O.B.T.~~ follows -

^{Old} 38" now 36" FIR N. 81° W, 23 1/2 ft.

Record N. 31° W. - Dead shows good
scar. NO TRACE of N.E. B.T. Fd -

at cor. point in place of old pipe
set 1" I.P. & BRASS CAP MKD "COUNTY
SURVEYOR'S OFFICE 1969

T195 533 | 534 T205 R9W " & MK.

New B.T. -

10" Maple N. 45° W 32 1/2 ft,
MKD. " T195 R9W 533 CS BT "

No other trees close - To N.E.
This cor. lies on very steep
southerly slope on E-W,
cutting line - clearcut to south.

June 19, 1969

V.R.T.
J.G.H.
V.D.P.

V.R. Tracy

O.K.
J.W.H.

6 #14 T20 R9W

C.S. File No. 53/66-50