

T205 R 536 | 531

Review Township COR T215 W 51 | 56 R10W

Fd. 3/4" I.P. & B.T.S called for in Ren #2
of T205 R10W-25 follows -

20" Now 28" Maple N. 14°W, 15 2/3 ft.

2 live - shows good scar - we do not open -

10" Now 16" Maple S. 27°W 11 2/3 ft.

2 live - shows good scar - we do not open

4" Now 20" Fir S. 77 1/4° E, 42 2/3 ft.

2 live - faint scar - we describe -

"T215 R10W 56 CS BT" - at cor. point
in place of I.P. set 1" I.P. & BRASS CAP

Mkd. "COUNTY SURVEYOR'S OFFICE
1968 T205 R10W 536 | 531 T215 R10W" &

Mk. new B.T. -

14" D. Fir N. 80° E, 83 1/2 ft.

Mkd. "T205 R10W 531 CS BT"

This cor. lies on very steep
S. slope approx 300 ft. N. of
SMITH RIVER ROAD. Deposit old cap
Pipe along side BRASS CAP.

March 27, 1968

URT
J.H.
UR

[Handwritten signature]

#25 - T205-10 #7-T21-10
#48-T205-10 #51-T21-11

J.W.B. C.S. File No. 53/66-163