

Renew & Witness Cor To  $\frac{1}{4}$  517/516 T205 RR  
Fd. 1953 G.L.O. Piped Brass cap nearly  
out of ground due to slide, &  
c.s. B.T. 5 as Recorded in Ren. # 6  
25 follows -

6" Hemlock N,  $82^{\circ}$  E, 11  $\frac{1}{2}$  ft,

Down & Dead -

8" Hemlock S,  $23\frac{1}{2}^{\circ}$  E, 4  $\frac{1}{2}$  ft.

scribe visible "  $\frac{1}{4}$  516 CS BT" we  
add "W.C." - 2 + TRU COR. set  
 $5\frac{1}{8}$ " x 30" I.R. & Move BRASS CAP  
South 30 ft. To point for Witness  
COR. Add "WIT. COR. 30 FT. N. TO COR." ON  
BRASS CAP, MK. New BT -

6" Hemlock N,  $84^{\circ}$  E, 28  $\frac{1}{2}$  ft,

Mkd. "W.C.  $\frac{1}{4}$  516 CS BT"

8" Hemlock S,  $67^{\circ}$  E, 21  $\frac{1}{2}$  ft,

Mkd. "W.C.  $\frac{1}{4}$  516 CS BT" (Ren. # 6 BT)

1953 FIR STUMP OF BT about to  
slide out. Witness COR. Now

Lies in BRUSH 10 ft. E. of Top  
of cut BANK ON E. Side of Road  
approx 50 ft. above Road.

July 10, 1968

\*H

~~C.S. FINE 53/66~~

D.V.P.T.  
J.W.B.  
W.P.

J.W.B.