

Renewal 16/15 7205 R11W

Found:

Remains of 5" Hemlock car Tree
Fragments of scire 1/4 S

38" D. Fir new stump S 20 1/2 W 8°
Shows good scar

30" D. Fir New stump S 55 1/2 E 5°
Badly Burnt

Renewal

Set Brass cap at 1/4 car M10
county Surveyors office

7205 R11W

1/4 S 16 / S 15

1968

New Bearing Tree

9" Hemlock S 60 E 72°
Scribed 1/4 S 15 CS BT

Also

2 Iron bolts 1/2" x 2 1/2" Bear South 15° - 20°

3-18-68
~~J. W. B.~~
~~J. W. B.~~
~~J. W. B.~~

O.K. J. W. B.

C. S. File No. 53/66-115

DIETZGEN NO. 385-5