


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

MEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 20S RANGE 6W
SECTION 30 CORNER E~~4~~
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
14" Fir	S 69° E	30.0	-	X	X	-
18" Fir	N 17° W	8.7	-	X	X	-

IDENTIFIED ON PHOTO:

GLO SURVEY RECORD

DATE: 1872

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
11" Fir	N 70° W	13	8.6	Fd. 13" Fir, Chopped out upper scar Fd. Scribing "13"
17" Fir	S 12° E	25	16.5	Fd. 18" Fir stub. Lower scar open "BT" visible Also later scribing "18" on surface of tree

SURVEY RECORD

DATE:

PRESENT CONDITION:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Sisal, Huckleberry, Vine Maple, Chinquapin and Dogwood

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 55° W ON MINUS (-) 58 %

NORTH: -47% 250' Cr. 2' wide C - S 60° W, Logged on West side & Virgin on East side

SOUTH: + 35% 45' top of spur ridge. Logged on West side & virgin on east side

EAST: + 45% Virgin timber

WEST: - 38% Logged

FROM CORNER

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

CORNER SET: 1/4" monel pipe along side of 3" x 3" x 24" MAG. DECL.: 20°

fir post scribed

BY: Robert Banta DATE: May 4, 1960

~~ENGINEER SURVEYOR~~
Instrumentman

UNDER THE SUPERVISION OF:

ASSISTED BY:

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
N 59° W	8.6	13" Fir	Face measurement
S 19° E	12.6	18" Fir stub	Face measurement

COPIES SENT TO:

SEAL

CS 53/102-4