


# PUBLIC LAND CORNERS

SPRINGFIELD  
SURVEY FILE

DWEYERHAEUSER TIMBER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 21 S RANGE 4 W  
SECTION 34 CORNER ADJ  
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
14" Fir	N 64 E	27.1	--	X	X	--
12" Fir	S 49 E	54.4	CS	X	X	--
14" Fir	S 69 W	7.0	CS	X	X	--
38" Fir Stump	N 48 W	13.6	1855	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Sisal - Dogwood

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) North ON MINUS (-) 40 %

NORTH: -40% Logged - Residual Fir

SOUTH: 40% Logged - Residual Fir

EAST: -2% Logged - Residual Fir

WEST: 4% Logged Residual Fir

FROM CORNER ↓

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Allen McCleary DATE: 4/10/61

ENGINEER - SURVEYOR  
LAND AGENT

ASSISTED BY: Robert Barba

UNDER THE SUPERVISION OF:

COPIES SENT TO:

SEAL PAGE 3

## GLO SURVEY RECORD

DATE: 1855  
CORNER POST

PRESENT CONDITION - (DESCRIBE FULLY -  
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

## ACCESSORIES:

	BEARING-	LINKS-	FEET-	
60" Fir	S 45 W	34	22.4	Rotted remains of large Fir Stump
60" Fir	S 75 E	28	18.5	Gone
20" Fir	N 45 E	29	19.1	Gone
24" Fir	N 40 W	20	13.2	38" Fir stump scribed "RM" visible

## SURVEY RECORD

Found in field:

Douglas County Brass Cap 1958

4" Fir	N 70 E	20.8	Scribed
12" Fir	S 48 E	54.5	Scribed
14" Fir	S 70 W	7.3	Scribed
8" Fir	N 63 W	28.0	Scribed

PRESENT CONDITION:

CORNER SET: Douglas County Brass Cap as found. MAG. DECL.: 20°

## BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
S 45 W	22.4	1855	Center of Stump
N 45 W	13.7	1855	Center of Stump

FILED  
RECEIVED

JUN 28 1961

PAGE 1

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

CS 53/104-3