


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH



TOWNSHIP 2 1 S RANGE 4 W
 SECTION 4 CORNER S 1/4
 COUNTY Douglas OREGON

GLO SURVEY RECORD

DATE: 1856
 CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
12" Fir	N 17 E	36	23-8	No trace
10" Fir	S 10 E	102	67-3	Low (4") remains rotted wood, bark
15" Cedar	-S 60 E - 109	IKS 71-9'		32" INC. Cedar stump-lower face scar visible.
24" Fir	- N 34 E 54	" 35-6'		36" badly rotted stump-face rotted away.

CORNER SET: 1"x30" Aluminum pipe set by distance MAG. DECL.: 20°
 from 1920 County Survey BTs.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
S 10 E	67	G16	Distance to root hole
S 56 E	71.9	C.S.	" " face
N 35 E	35.6	"	" " "

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG.B.T.	"W" NAIL	PLATE	BRASS DISC
12" Fir	S 19 W	37.5	----	X	X	----
14" Fir	N 20 W	12.3	----	X	X	----

IDENTIFIED ON PHOTO: NO

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Dogwood, hazel, fern
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) _____ %

NORTH: +14% Logged = 20 - 40 year reprod.
 SOUTH: -22% " Recently re-logged
 EAST: Level "
 WEST: Level " 377' plate West side dirt road on Chinquapin

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: Glen M. Chumley DATE: 1/21/60
ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY: Robert Barta

COPIES SENT TO: _____

CS 53/104-4