


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH



TOWNSHIP 22S RANGE 4W
SECTION 4 CORNER S $\frac{1}{4}$
COUNTY Douglas OREGON

GLO SURVEY RECORD

DATE: 1855
CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

No trace of Original

ACCESSORIES:

BEARING-	LINKS-	FEET-	
<u>20" Fir</u>	<u>S7W</u>	<u>9</u>	<u>5.9</u>
			<u>Found rotted, down fir-hard to identify</u>
<u>9" Cedar</u>	<u>N13E</u>	<u>* 1510</u>	<u>996.6</u>
			<u>38" Inc. Cedar Orig. Scribing visible-</u>
			<u>newly scribed.</u>
			<u>*?</u>

County SURVEY RECORD
DATE: 1958

PRESENT CONDITION:

Found in field:
Brass Cap dated 1958 set by Douglas
County Survey.

38" Inc. Cedar-Scribed "184 CSET"

4" White Fir - " "189 CSBT"

CORNER SET: Brass Cap Set by Douglas MAG. DECL.: 20°

County Survey 1958

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
<u>S7W</u>	<u>6.0</u>	<u>GLO</u>	
<u>N3E</u>	<u>9.4</u>	<u>GLO</u>	<u>Measured to Old Scribing.</u>
<u>N3E</u>	<u>8.6</u>	<u>CS</u>	<u>Measured to 1958 Scribing.</u>
<u>S7W</u>	<u>24.8</u>	<u>CS</u>	<u>" " "</u>

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
<u>38" Incense Cedar</u>	<u>N10E</u>	<u>8.9</u>	<u>GLO CS</u>	<u>X</u>	<u>X</u>	<u>-</u>
<u>38" " "</u>	<u>S25W</u>	<u>32.2</u>	<u>-</u>	<u>X</u>	<u>X</u>	<u>-</u>

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Salal

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) East ON MINUS (-) 11 %

NORTH: Level - Logged to East and West

SOUTH: - 3% - Old Growth

EAST: -11% - Logged to North, Old growth to South

WEST: +12% 300' then descend. (430' dirt road and 750' to powerline)

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Alex McChesney DATE: 4/2/59
ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

PAGE 3

CS 53/105-1