


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W

SECTION 10 CORNER N 1/2

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
52" Incense Cedar stump	N 7 E	46.0	---	X	X	---
16" Fir	S 57 E	19.0	---	X	X	---

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) --- ON MINUS (-) --- %

Slope: S 30 W - 30% for 65' then - 70%

NORTH: + 8% 60' then descend into draw C-SW. Current relog.
 SOUTH: - 30% 50' then -65% for 300' to draw C-S
 EAST: + 15%
 WEST: - 15% 25' then -55% for 380' to creek C-S

FROM CORNER

GLO SURVEY RECORD

DATE: 1884
CORNER Post and stone

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

No trace of original stone or post.

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
12" Laurel	N 47 W	55	36.3	Gone
24" Fir	S 32 W	34	22.4	Found 30" Fir stump--No visible scribing
GLO 1903 - No mention of 1884 stone Found post and 24" Fir Bt New Bt:				See above
8" Cedar	N 10 W	41	27.1	Scribing visible on 14" Incense Cedar

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: Found 1" galvanized iron pipe used as hub by MAG. DECL.: 20°

Woodard Lumber Company

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -
S 32 W	22.4	1884
N 8 W	27.1	1903

PAGE 1

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

By: Ellen McFarlane DATE: August 26, 1963

ENGINEER & SURVEYOR
LAND AGENT

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/105-5