


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W
SECTION 10 CORNER S E
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE: _____ MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
45" Fir	S 48 E	44.6	—	x	x	—
10" Fir	N 23 E	23.5	—	x	x	—
10" Incense Cedar	N 71 W	69.7	—	x	x	—
10" Fir	S 39 W	38.0	—	x	x	—

IDENTIFIED ON PHOTO: _____

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) N 35 W ON MINUS (-) 25 %

NORTH: -16% To west logged 5-6 years; to East uncut OG fir
SOUTH: +13% To east " " " " West " " "
EAST: +28% To north uncut OG fir; To south logged about 7-8 years
WEST: -22% To south uncut OG fir
To north logged 5-6 Years

FROM CORNER

GLO SURVEY RECORD
DATE: 1855
CORNER Post PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)
Gone

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
8" Fir	S 10° E	31	20.5	32" Fir windfall uprooted face not opened.
5" Laurel	S 34 W	20	13.2	No trace
8" Fir	N 15 E	35	23.1	Broken off near scribing scribing visible
16" Fir	N 28 W	66	43.6	30" Fir, windfall 1962 open face & scribing

WCO SURVEY RECORD
DATE: 1957
PRESENT CONDITION: _____
26" F N 28 W 43.5 Down
18" F N 41 E 27.1 "
22" F S 68 W 37.0 "
40" F S 45 E 44.0 See new reference

CORNER SET: Found monel at proper location MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
<u>S 68 E</u>	<u>20.5</u>	<u>1855</u>	<u>To stump hole & approx. line position</u>
<u>N 12 E</u>	<u>22.8</u>	<u>"</u>	<u>Measured to scribing</u>

WORK DONE FOR W. CO. _____ FIELD NOTES IN BOOK: _____
BY: William R. Hill DATE: 1/21/63
~~ENGINEER - SURVEYOR~~
Land Agent
ASSISTED BY: _____
COPIES SENT TO: _____
UNDER THE SUPERVISION OF: _____

CS 53/105-8