


PUBLIC LAND CORNERS

SPRINGFIELD SURVEY FILE

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W
SECTION 10 CORNER W 1/4
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
36" Incense Cedar (Orig. B.T. rescribed 1958 by D. Co.)	N 59° E	11.9	X	X	X	---
13" Doug. Fir	S 41° W	46.3	1958 Doug. Co. X	X	X	---

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Mixed stand of old growth & 2nd growth Doug. Fir.

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) North ON MINUS (-) 58 %

NORTH: -53%; 300' N logged to East of Sec. line; otherwise all unlogged in vicinity of cor.

SOUTH: + 35%, old, well blazed line to S W Cor. of Sec. 10 130' to top of ridge and high point in same - Ridge E & W

EAST: -11%; small opening in timber, 75' in diameter heavily stocked to 15 yr. old Doug. Fir immediately East of cor.

WEST: -8% uncut 2nd growth

FROM CORNER ↓

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Wilt DATE: 5/29/64
ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

PAGE 3

GLO SURVEY RECORD				PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)
CORNER	DATE:			
<u>Post</u>	<u>1856</u>			<u>Gone</u>
ACCESSORIES:				
	BEARING-	LINKS-	FEET-	
<u>12" Cedar</u>	<u>N 56° E</u>	<u>19</u>	<u>12.5</u>	<u>36" Incense Cedar; face chopped out face rotted but chip shows good negative scribing</u>
<u>30" Fir</u>	<u>S 55° W</u>	<u>46</u>	<u>30.4</u>	<u>Gone</u>
Douglas County SURVEY RECORD				
<u>Set brass cap at corner</u>	<u>DATE: 1958</u>			<u>Good Condition</u>
<u>Rescribed new 36" original Incense Cedar B.T.</u>	<u>N 56° E</u>	<u>12.5'</u>		<u>Good Condition, face open</u>
<u>13" Red Fir</u>	<u>S 41° W</u>	<u>47.1'</u>		<u>Good Condition, face healed over</u>

CORNER SET: Found new post & Doug. Co. brass cap MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
<u>N 58° E</u>	<u>12.5</u>	<u>1856 & 1958</u>	<u>To center of tree</u>
<u>S 41° W</u>	<u>47.1</u>	<u>1958</u>	<u>To center of tree</u>

PAGE 1

CS 53/105-10