SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W

SECTION 14 CORNER N¼

COUNTY Lane & Douglas OREGON



GLO SURVEY RECORD

DATE: 1855

CORNER Post

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
8" Fir	S 70° W	103	68.0	38" Fir stump - scribing visible
6" Laurel	N 75° W	2 (21)	--	No trace

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

No trace

Weyerhaeuser Co. SURVEY RECORD

DATE: July 19, 1957

Monel pipe & Cedar post

PRESENT CONDITION: December 29, 1962

8" Fir	N 62° W 16.0'	Found
24" Inc. Cedar	S 81° W 62.0'	Plate & "W" nail O.K.
		24" I. Cedar stub --renewed plate, "W" nail O.K.

CORNER SET: 1" Aluminum pipe and cedar post MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
S 70½° W	67.5	GLO	38" Fir Face measurement
S 81° W	62.0	WCo	24" Inc. Cedar
N 62° W	16.0	"	8" Fir

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
8" Fir	S 28 W	70.0	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Field fern opening

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 50° E ON MINUS (-) 12 %

FROM CORNER -

NORTH: + 10% Virgin timber

SOUTH: - 10% Logged

EAST: - 7% Logged

WEST: + 8% Logged on South side & virgin on North side

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Hill DATE: December 29, 1962

~~CIVIL ENGINEER~~ ~~SURVEYOR~~

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/105-11