


SPRINGFIELD
 SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W
 SECTION 14 CORNER S W
 COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20'

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
20" Fir	N 76° E	20.4		x	x	
28" Fir	S 52° E	38.0	x	x	x	
48" Fir	S 70° W	13.0	x	x	x	
32" Fir	N 51° W	9.9	x	x	x	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) _____ %

NORTH: _____
 SOUTH: _____
 EAST: _____
 WEST: _____

FROM CORNER

GLO SURVEY RECORD

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

DATE: 1879
 CORNER Post

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
10" Fir	N 54° E	20	13.2	Gone
12" Fir	S 52° E	50	33.0	Fd 28" Fir
36" Fir	S 77° W	22	14.5	Fd 48" Fir
24" Fir	N 47° W	18	11.9	Fd 32" Fir

SURVEY RECORD DATE:

PRESENT CONDITION:

CORNER SET: Fd 3/4" 1 pipe & 2"x2"x2' yew post MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-	
S 52° E	38.0	GLO	Now 28" Fir
S 70° W	13.0	GLO	Now 48" Fir
N 51° W	9.9	GLO	Now 32" Fir

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Nick Juliano DATE: Nov. 1958
 ENGINEER - SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL

CS 53/105-12

5