


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W
SECTION 17 CORNER S 1/4
COUNTY Douglas OREGON



#118

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
6" Fir	S 51° E	15.6	---	X	X	#2149
6" Fir	S 67° W	36.1	---	X	X	#2149

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Grass (pasture)
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) N 15° E ON MINUS (-) 15 %

NORTH: - 10% Grass native pasture

SOUTH: + 5% "

EAST: + 30% 20 year old Douglas Fir reproduction

WEST: 0% "

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Felt DATE: 5/15/62
ENGINEER-SURVEYOR
Land Agent

ASSISTED BY: Glen McChesney

UNDER THE SUPERVISION OF:

COPIES SENT TO:

SEAL PAGE 3

GLO SURVEY RECORD

DATE: 1855
(Gordon & Gardener)

CORNER Post

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
20" Fir	S 24° E	15	9.9	No evidence found
24" Fir	N 20° W	65	39.0	"

SURVEY RECORD DATE:

PRESENT CONDITION:

CORNER SET: 1 inch Aluminum pipe MAG. DECL.: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS 53/105-13