


PUBLIC LAND CORNERS

SPRINGFIELD
SURVEY FILE

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W
SECTION 17 CORNER PT "X"
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
22" Fir	S 39° E	34.3	---	X	X	#2149
18" Fir	S 24° W	47.8	---	X	X	#2149

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Bracken fern and hazel brush
 (USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
 SLOPE FACES (GIVE BEARING IN DEGREES) N 20° E ON MINUS (-) 26 %

NORTH: - 26% 25 year old Douglas Fir reproduction
Scattered 60 year old residual 2nd growth fir
 SOUTH: + 23% "
 EAST: - 42% "
 WEST: 0 "

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Nott DATE: 5/11/62
~~ENGINEER - SURVEYOR~~
 Land Agent

UNDER THE SUPERVISION OF:

ASSISTED BY:

COPIES SENT TO:

SEAL PAGE 3

GLO SURVEY RECORD

DATE: (None)

CORNER

ACCESSORIES:

BEARING-	LINKS-	FEET-

SURVEY RECORD
DATE:

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION:

CORNER SET: 1 - inch Aluminum pipe MAG. DECL.: 20 - E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -

CS 53/105-15