


SPRINGFIELD  
SURVEY FILE

# PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W  
SECTION 17 CORNER W 1/16 "O"  
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
6" Fir	S 50° E	17.2	---	X	X	X
3 1/4" Fir stump	N 79 1/2° W	22.1	---	X	X	X

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Hazel brush  
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)  
SLOPE FACES (GIVE BEARING IN DEGREES) North ON MINUS (-) 25 %

FROM CORNER -

NORTH: - 25% West: oak with 2nd growth fir logged out about 8 years  
East: grass pasture

SOUTH: + 30% East: 25 year old fir reproduction  
West: Oak with 2nd growth fir logged out about 8 years

EAST: 0% North: Grass pasture  
South: 25 year old fir reproduction

WEST: + 5% North & South: oak with 2nd growth fir logged out about 8 years

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Hill DATE: 5/15/62  
ENGINEER SURVEYOR  
Land Agent  
ASSISTED BY: Glen M. Chesney

UNDER THE SUPERVISION OF:

COPIES SENT TO:

SEAL PAGE 3

GLO SURVEY RECORD

DATE: (None)

CORNER

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

ACCESSORIES:

BEARING-	LINKS-	FEET-

None SURVEY RECORD DATE:

PRESENT CONDITION:

CORNER SET: Aluminum pipe

MAG. DECL.: 20° E

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS 53/105-17