


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W
SECTION 21 CORNER E 1/4
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
18" Fir	N 59° E	5.3	--	X	X	--
20" Fir	S 34° W	33.3	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Salal, fern & virgin timber

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 40 W ON MINUS (-) 47 %

NORTH: - 45% 100' draw C - west logged on west side
virgin timber on east side

SOUTH: + 21% virgin timber

EAST: + 45% virgin timber

WEST: - 46% virgin timber on south & logged on north side

FROM CORNER

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: Robert Brito DATE: Sept. 17, 1962

UNDER THE SUPERVISION OF:

ASSISTED BY: David Daniels

Dick Traylor

COPIES SENT TO:

SEAL

PAGE 3

GLO SURVEY RECORD

DATE: 1855

CORNER Post

ACCESSORIES:

BEARING-	LINKS-	FEET-	PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)	
36" Fir	N 34° E	69	45.5	Gone - Haines "T" iron & 1/2" G.I.P.
36" Fir	N 73° W	51	33.7	42" Fir - bark scribing visible
				Badly rotted & burned remains

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER ~~STAKE~~ 1/2" G.I. pipe & Haines "T" MAG. DECL.: 20°

Iron stake

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
N 35° E	42.7	GLO	42" Fir - face measurement
N 73° W	34.0	GLO	Rotted remains center of remains

PAGE 1

CS 53/105-18