


PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W
SECTION 21 CORNER N 1/16 "G"
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
12" Fir	N 18 E	11.6	—	x	x	#2149
18" Fir	S 25 W	12.6	—	x	x	#2149

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: 30 to 40 yr. old d. fir; little or no brush
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) S70°W ON MINUS (-) 28 %

NORTH: + 10% ; 30' to top ridge bearing NW & SE; 30-40 yr. fir
SOUTH: -20% ; 225' to fire road; 30-40 yr. old fir
EAST: +21% ; 60' to above fir road; 30-40 yr. old fir
WEST: -24% ; 300' to logged area to south & old growth fir uncut to north

FROM CORNER ↓

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William P. Hill DATE: Sept. 17, 1962
ENGINEER - SURVEYOR
Land Agent

UNDER THE SUPERVISION OF:

ASSISTED BY:
Dale Beckham (BLM)
Ed Ware

COPIES SENT TO:

SEAL PAGE 3

GLO SURVEY RECORD			PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)
CORNER	DATE:		
ACCESSORIES:			
BEARING-	LINKS-	FEET-	
SURVEY RECORD			PRESENT CONDITION:
DATE:			

CORNER SET: 1" Aluminum pipe & 2" fir post. MAG. DECL.: 20°
Set by single proportion

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS53/105-19