


# PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W  
SECTION 21 CORNER W 1/4  
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
14" R. cedar	N 24° E	9.7	--	X	X	--
10" R. cedar	S 27° W	28.0	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Fern

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) S 80° W ON MINUS (-) 50 %

NORTH: + 8%

SOUTH: - 5%

EAST: + 48%

WEST: - 48%

FROM CORNER -

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: Robert Barthe DATE: 9-13-62

~~ENGINEER - SURVEYOR~~

ASSISTED BY: Dale Beckham (BIM)

Ed Ware (BIM)

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

GLO SURVEY RECORD

DATE: 1855

CORNER Post

ACCESSORIES:

	BEARING-	LINKS-	FEET-
6" Maple	N 62° E	34	22.4
40" Fir	S 50° W	23	15.2

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

Gone - found Brass cap set by county surveyor in 1961

12" maple - chopped on - no scribing

40" x 12' fir snag - chopped on - no scribing

SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: Brass cap as set by county MAG. DECL.: 20°

Surveyor

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	
N 62° E	21.5	GLO	12" maple face measurement
S 50° W	15.0	"	40" Fir snag face measurement

PAGE 1

CS 93/105 - 22