SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22S RANGE 4W

SECTION 33 CORNER C 1/4

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

County SURVEY RECORD

DATE: 1915

PRESENT CONDITION:

9" Oak-N3 1/2E-778 lks- 513.5'	Gone
24 " Maple- S65E-249 lks- 164.3 '	Gone
14 " Ash - N15W-923 lks- 609.2'	20" Ash - 2 faces not opened
7 " Oak - S 23°35' W-469 lks - 309.5 '	24" Oak - Scribing Visible

CORNER SET: A Weyerhaeuser Company MAG. DECL.: 20°

"W" Nail in paved county road set by distances from NW and SW CS BTs

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -
N16W	609.2	CS
S22W	309.5	CS

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
3/4" iron rod "CR R/W POT 110 + 50 "	N4E	34.0	-	-	-	-
" " " " " "	S 7 1/2 E	26.5	-	-	-	-
10 " Power Pole	N20E	36.5	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Paved County Road

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) ON MINUS (-) %

FROM CORNER I

NORTH:

SOUTH:

EAST:

WEST:

WORK DONE FOR W. T. CO.: FIELD NOTES IN BOOK:

BY: Glen McChesney DATE: 3/23/60
~~ENGINEER - SURVEYOR~~ LAND AGENT

ASSISTED BY: Robert Barta

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

CS 53/05-23