SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22S RANGE 4W

SECTION 33 CORNER CS 1/16 "M"

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE:

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

County SURVEY RECORD

DATE: 1915

40" Fir N85E 20 lks. - 13.2'	Found 44" Fir Stump - No scribing visible- Had been chopped. Probably was bark scribed
8" Fir S67W 32 lks. - 21.1	Gone

PRESENT CONDITION:

CORNER SET: Found old 1½" iron pipe and 4" square MAG. DECL.: 20°

post S85W 13.2' from 44" Fir Stump.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -
N85E	13.2	CS

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
22 " Fir	N48E	23.0	-	X	X	-
5 " Fir	S24W	12.4	-	X	X	-

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Fern and Poison Oak

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) North ON MINUS (-) 20 %

FROM CORNER -

NORTH: -20% logged

SOUTH: ±17 % logged

EAST: Level logged 40 ' to N-S fence and 60' to dirtroad

WEST: Level logged

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Glen McChesney DATE: 3/23/60
~~ENGINEER - SURVEYOR~~
Land Agent

ASSISTED BY: Robert Barta

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/105-24