


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH
TOWNSHIP 22 S RANGE 4 W
SECTION 34 CORNER C 1/4
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
14" Fir	S 66° E	14.4	--	X	X	--
12" "	S 18° W	16.6	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Grass
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) North ON MINUS (-) 12 %

NORTH: - 12% Open Field

SOUTH: + 10% 2nd growth

EAST: + 3% 190' S County road. Fence line.

WEST: + 4% Fence line.

FROM CORNER:

GLO SURVEY RECORD			PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)
CORNER	DATE:		
ACCESSORIES:			
BEARING-	LINKS-	FEET-	
SURVEY RECORD			PRESENT CONDITION:
DATE:			

CORNER SET: Fd. 1 3/4" Pipe and 4" square oak post MAG. DECL.:
scribed C.S.

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -

WORK DONE FOR W. T. CO.: _____ FIELD NOTES IN BOOK: _____

BY: William L. Williams DATE: Jan. 5, 1961
ENGINEER - SURVEYOR
 Land Agent

ASSISTED BY: Robert Barta

COPIES SENT TO: _____

UNDER THE SUPERVISION OF: _____

CS 53/105-24