


SPRINGFIELD
SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W
SECTION 34 CORNER CE 1/16
COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
14" Fir	N 16° E	30.0	C S BT	X	X	--
62" Inc. Cedar	N 83° E	10.5	--	X	X	--

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: _____
(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)
SLOPE FACES (GIVE BEARING IN DEGREES) _____ ON MINUS (-) 9/0

NORTH: - 12% Logged

SOUTH: + 76% Logged on West side, virgin on East side.

EAST: + 67. " " North " " South side.

WEST: - 37% Logged

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: _____

BY: William H. Hilbate DATE: Jan. 6, 1961
ENGINEER - SURVEYOR

ASSISTED BY: Robert Barta

COPIES SENT TO: _____

UNDER THE SUPERVISION OF:

GLO SURVEY RECORD

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

DATE: _____

CORNER _____

ACCESSORIES:

BEARING-	LINKS-	FEET-

SURVEY RECORD
DATE: _____

PRESENT CONDITION: _____

CORNER SET: Fd. Haines "T" iron monument MAG. DECL.: _____

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS 53/105-27