

# PUBLIC LAND CORNERS


SPRINGFIELD  
SURVEY FILE

WEYERHAEUSER TIMBER COMPANY  
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W

SECTION 34 CORNER C W 1/16

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 2 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
<del>XXXXXX</del> 14" W. Oak	N 35° E	21.0	CSBT	X	X	
14" W. Oak	N 08° W	79.6		X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Grass

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) \_\_\_\_\_ ON MINUS (-) %

Southeast edge of County Road

NORTH: 4 6% Open Field 15' & County Road

FROM CORNER

SOUTH: - 13% 100' Creek C- S 40° W

EAST: - 8% 130' Creek C- S 40° W

WEST: 4 2% Field

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK: \_\_\_\_\_

BY: William P. Pitt DATE: Jan. 18, 1961

ENGINEER & SURVEYOR

UNDER THE SUPERVISION OF:

ASSISTED BY: Robert Barta

COPIES SENT TO: \_\_\_\_\_

SEAL

PAGE 3

## GLO SURVEY RECORD

DATE: \_\_\_\_\_

CORNER \_\_\_\_\_

PRESENT CONDITION - (DESCRIBE FULLY -  
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

### ACCESSORIES:

BEARING-	LINKS-	FEET-

C S SURVEY RECORD  
DATE: ?

PRESENT CONDITION: \_\_\_\_\_

Found in field: 12" W. Oak  
both fences open. Scribing  
"CS BT" visible. See Page 2

CORNER SET: 1" x 30" Alum. Pipe

MAG. DECL.: \_\_\_\_\_

### BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS53/105-29