

SPRINGFIELD
SURVEY FILE


PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W

SECTION 34 CORNER SE 1/16

COUNTY Douglas OREGON



ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
10" Maple	S 76° E	13.2		X	X	
28" W. Fir	N 25° W	9.9	CSBT	X	X	

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Sisal, Sword Fern, Vinemapple

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) South ON MINUA 48 %

NORTH: 48% 40' & County Rd. Logged on West and Virgin timber on East side.

SOUTH: 47% 15' Creek C - West Logged

EAST: 8% 140' Creek C - S 85° W Logged on South side and Virgin on North side

WEST: 10% Logged

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: William L. Hill DATE: Jan. 5, 1961
ENGINEER-SURVEYOR
Land Agent

UNDER THE SUPERVISION OF:

ASSISTED BY: Robert Barta

COPIES SENT TO:

GLO SURVEY RECORD

DATE: _____
CORNER _____

ACCESSORIES:

BEARING-	LINKS-	FEET-

CS SURVEY RECORD
DATE: ?

PRESENT CONDITION - (DESCRIBE FULLY -
USE PAGE 2 IF NEEDED FOR EXPLANATION.)

PRESENT CONDITION: _____

Fd in field:
Old scribed post and 28" W. fir
with two healed faces. See p. 2

CORNER SET: Fd. remains old scribed post, MAG. DECL.: _____

stone and 2" square Fir post

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY-

CS 53/105-32