PUBLIC LAND CORNERS

WEYERHAEUSER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W

SECTION 34 CORNER W 1/16 = "B"

COUNTY Douglas OREGON



GLO SURVEY RECORD

DATE: (None)

CORNER

ACCESSORIES:

	BEARING-	LINKS-	FEET-

PRESENT CONDITION - (DESCRIBE FULLY - USE PAGE 2 IF NEEDED FOR EXPLANATION.)

(None) SURVEY RECORD

DATE:

PRESENT CONDITION:

CORNER SET: 1" Aluminum Pipe MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -	

PAGE 1

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20°

	BEARING	FEET	ORIG. B.T.	"W" NAIL	PLATE	BRASS DISC
18" fir	N 65° W	18.3	---	X	X	---
14" fir	S 25° W	13.0	---	X	X	---

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: 2nd Growth fir

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) South ON MINUS (-) 37 %

FROM CORNER -

NORTH: + 27%; uncut 2nd Growth fir

SOUTH: - 37%; Logged; scattered 2nd Growth fir

EAST: 0%; Logged to South, uncut 2nd Growth to North

WEST: 0%; Logged clear cut to South, uncut 2nd Growth to North.
About 80' to dirt logging road bearing N & S

WORK DONE FOR W. CO.

FIELD NOTES IN BOOK:

BY: William L. Fitts DATE: August 29, 1963
ENGINEER - SURVEYOR

ASSISTED BY:

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

PAGE 3

CS 53/105-33