SPRINGFIELD SURVEY FILE

PUBLIC LAND CORNERS

WEYERHAEUSER TIMBER COMPANY
SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE 4 W

SECTION 36 CORNER S W

COUNTY Lane OREGON



GLO SURVEY RECORD

DATE: 1854

CORNER Post

PRESENT CONDITION – (DESCRIBE FULLY – USE PAGE 2 IF NEEDED FOR EXPLANATION.)

No trace

ACCESSORIES:

	BEARING–	LINKS–	FEET–	
10" Fir	N 55 W	33	21.8	No trace
11" Redwood	N 38 E	11	7.3	"
10" Redwood	S 10 E	8	5.3	"
12" Maple	S 40 W	47	31.0	"

County _____ SURVEY RECORD

DATE: 1898

SW & NW Bts gone - Found

SE & NE Bts - Marked new:

36" Fir N 11 W 73 lks. CS BT
36" Cedar S 54 W 154 lks. "
20" Fir N 52 E 113 lks. "

PRESENT CONDITION:

No trace
"
"
"

CORNER SET: 3" Aluminum square nailed into 12" Fir log. Corner set by GLO distance between line trees.

MAG. DECL.: 20°

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING–	FEET–	SURVEY–	

ACCESSORIES ADDED THIS DATE:

MAGNETIC DECLINATION 20

	BEARING	FEET	ORIG.B.T.	"W" NAIL	PLATE	BRASS DISC
12" Red Cedar	N 32 E	22.0	----	X	X	2149
50" Fir	S 79 E	39.9	----	X	X	"
32" Red Cedar Stump	S 02 W	31.4	----	X	X	"
66" Fir	N 45 W	28.6	----	X	X	"

IDENTIFIED ON PHOTO:

INFORMATION ON LOCATION OF CORNER AS NOW SET:

GROUND COVER: Logging landing - ~~mix~~ ~~mix~~ pile of small logs

(USING FORM LINES SKETCH TOPOG AT CORNER ON PAGE 2 PLAT)

SLOPE FACES (GIVE BEARING IN DEGREES) N 75 W ON MINUS (–) 23 %

FROM CORNER –

NORTH: - 6% Virgin timber West

SOUTH: +16% Logged to West-Virgin timber to East except blowdown logged near corner.

EAST: +28% Virgin timber

WEST: -15% Logged to South - Virgin timber to North

WORK DONE FOR W. T. CO.:

FIELD NOTES IN BOOK:

BY: Glen McCherney ~~ENGINEER-SURVEYOR~~ DATE: 2/29/60

ASSISTED BY: Robert Barta

COPIES SENT TO:

UNDER THE SUPERVISION OF:

SEAL

CS 53/105-34