

PUBLIC LAND CORNER'S

WEYERHAEUSER TIMBER COMPANY
 SPRINGFIELD BRANCH

TOWNSHIP 22 S RANGE _____
 SECTION 34 CORNER _____
 COUNTY DOUGLAS OREGON



GLO SURVEY RECORD

DATE: 1855

CORNER Post

PRESENT CONDITION - (RECORD PAGE 2 IF NEEDED FOR EXPLANATION)

ACCESSORIES:

	BEARING-	LINKS-	FEET-	
12" Flc	N 14° E	15	9.5	Dark Colored
12" Flc	S 82° W	165	108.0	Double Stubs Burned
10" Flc	N 20° W	27	17.0	Chopped, Barled over
6" Laurel	S 20° E	39	25.7	No Trace

SURVEY RECORD

DATE: _____

PRESENT CONDITION _____

CORNER SET: Found 3/4" Galv. Pipe and 1" Iron with W. Haines Cap. MAGNETIC DECLINATION: _____

BEARING AND DISTANCE TO ABOVE IDENTIFIED SURVEY ACCESSORIES:

BEARING-	FEET-	SURVEY -
N 14 E	9.5	GLO
S 82 W	109.0	GLO
N 20 W	17.8	GLO

CS / 105 - 38

